

## Infrastructure

The final category included in the windshield survey is infrastructure. The survey recorded the presence of streetlights, and the City of Georgetown provided data on existing stormwater infrastructure in San José.

### Streetlights

Streetlights are found on 20% of parcels in San José, with at least one streetlight on each street in the neighborhood. Streetlights are most prevalent on Pine Street and are the least prevalent on San José Street.

### Stormwater


There is limited stormwater infrastructure within the San José neighborhood. Existing stormwater infrastructure is concentrated around the exterior of the neighborhood, near East 15th Street and San José Park. A concrete drainage swale runs along Maple Street, from San José Park to East 19th Street.

### *Key Findings*

- Streetlights are on 20% of parcels in the neighborhood;
- There is limited street lighting around San José Park; and
- Existing stormwater infrastructure is concentrated on the exterior of the neighborhood.

# There is Limited Street Lighting in the Neighborhood

Figure 25: Street Lights in San José



# There is Limited Stormwater Infrastructure in San José

Figure 26: Existing Stormwater Infrastructure in San José



## Transportation Strengths, Opportunities, Weaknesses and Threats

### Strengths

- The majority of lots have access to existing off-street parking;
- The neighborhood's proximity to San José Park and Purl Elementary School;
- The splash pad at San José Park; and
- The lighted basketball court.

### Weaknesses

- Existing streets in the neighborhood are narrow;
- There is a lack of stormwater infrastructure in the neighborhood;
- There is limited parking near San José park;
- Lack of covered shade and picnic areas; and
- Few existing streetlights in the neighborhood.

### Opportunities

- Improve pedestrian access around San José Park;
- Improve pedestrian access between the neighborhood and Purl Elementary School;
- Implementing speed reduction techniques in San José; and
- Increase stormwater management infrastructure in the neighborhood.

### Threats

- Continued speeding in the neighborhood;
- Increased traffic due to visitors to San José Park;
- Future flooding events in the neighborhood; and
- Street widths along San José impede emergency services when parking is present.



Source: Austin.com